For information about other American International automotive accessories visit our website at: http://www.aius.net









WWW.AIUS.NET

2500 East Francis Street Ontario, CA 91761, U.S.A. USA Sales (800) 336-6500 Canada Sales (888) 922-3006

CUSTOMER HELP LINE

USA 800-323-4329 • Canada 800-245-8777

iTTR992

VEHICLE APPLICATIONS

Toyota 2003-09 4-RUNNER (Base Sport Edition) 2003-09 4-RUNNER SR 5 2000-05 CELICA 2000-05 ECHO 2007-14 FJ CRUISER 2001-07 HIGHLANDER 2013 HIGHLANDER 2005-08 MATRIX 2000-05 MR2 SPYDER 2001-05 RAV4 2012-14 YARIS 2007-11 YARIS (w/o 3" Radio Display) Scion 2013-14 FR-S 2012-14 IQ 2005-14 TC 2004-06 XA 2004-12 XB 2008-14 XD

©2015 AMERICAN INTERNATIONAL INDUSTRIES, INC.

KIT ASSEMBLY INSTRUCTIONS

- 1. Attach the factory metal mounting brackets to the left and right sides of the Double Din aftermarket radio component or (2) single Din aftermarket radio components using the screws removed from the factory radio.
- Align the left and right TTR-992 Trim pieces to the appropriate sides of the aftermarket radio component or components and attach using the screws supplied with radio when possible.

DASH DISASSEMBLY & RADIO REMOVAL INSTRUCTIONS

2000-05 TOYOTA CELICA

- 1. Gently lift upward shift lever trim panel and slide back, disconnect harness and remove.
- 2. Remove the (4) knobs from the A/C-heater controls.
- 3. Remove the (2) Phillips screws below the A/C-heater controls.
- 4. Remove the (2) Phillips screws securing the bottom edge of the climate controls to the subdash.
- 5. Gently pry upward and towards you the radio trim panel/climate control trim bezel and remove.
- 6. Remove the (4) 10mm bolts securing the radio.
- 7. Slide the radio forward, disconnect the wire harnesses and antenna lead and remove the radio.

2000-05 TOYOTA ECHO

- 1. Remove the (2) outer A/C-heater control knobs.
- 2. Remove the (2) Phillips screws from these locations.
- 3. Gently unsnap the A/C-heater control panel, disconnect the harnesses and remove.
- 4. Gently unsnap the trim from around the radio and remove.
- Depress the tabs securing the heater controls in place and pull slightly forward and upward to allow access to the top radio mounting screws.
- 6. Remove the (4) Phillips screws securing the radio.
- 7. Gently slide the radio forward and disconnect the wire harnesses and antenna lead and remove the radio.

2000-05 TOYOTA MR2 SPYDER

- 1. Gently remove the screw cover caps from the lower sides of the radio mounting rails.
- 2. Remove the (2) phillips screws from the base of each side of the main radio support bracket covers, and remove the covers.
- 3. Remove the (4) phillips screws securing the radio to the sub-dash.
- 4. Remove the (4) screws securing the Drink Tray/Ashtray assembly, and lower the assembly out of the way.
- 5. Gently pull the radio forward.
- 6. Disconnect the harness and antenna lead from the radio and remove the radio.

2003-09 TOYOTA 4-RUNNER SR 5 2003-09 4-RUNNER SPORT EDITION (Select Models)

- 1. Open the center pocket below the climate controls and remove the (1) 10 mm bolt.
- 2. Carefully Unclip the center console section with ashtray trim, disconnect the harness and remove console section.
- 3. Carefully lift the center console side covering and remove
- 4. Remove the (2) lower 10 mm bolts from the bottom of driver side under dash panel.
- 5. Carefully pull drivers side under dash panel outward and lay out of the way.
- 6. Remove the (1) 10mm bolt at the lower edge of the radio trim bezel on the driver side.
- 7. Unclip the trim from the front of the center console pocket.
- 8. Carefully pry outward the climate control pod, disconnect the wire harness and remove ipod.
- 9. Remove the (2) 10mm bolts from behind the climate control location.



2008-14 SCION xD

DASH DISASSEMBLY

- 1. There is a secondarily sub dash bezel between the main dash board and the actual dash bezel.
- 2. Carefully remove the dash bezel starting at the top and work to the bottom just above the climate controls
- 3. Unplug the necessary harness to remove bezel
- 4. Remove (4) Philips screws securing factory radio in place
- 5. Unplug radio harnesses and remove radio.

2005-10 SCION TC

DASH DISASSEMBLY

- 1. Set the parking brake.
- Insert key into the ignition switch and turn to the on position (DO NOT START THE CAR!!) then depress the brake pedal and place the shifter lever into the low position.
- 3. Carefully pry upward on the center console trim from around the shifter, disconnect the 12 Volt receptacle harness from the rear of the trim and remove trim.
- Carefully pry Radio/Climate control trim bezel forward, starting at the bottom, disconnect the harness attached to the rear of the Climate controls and remove bezel.
- 5. Remove the (2) Phillips screws securing the lower factory radio brackets.
- 6. Remove the (2) 10 mm nuts securing the top radio mounting brackets.
- 7. Carefully pull radio forward, disconnect the harness or harnesses and antenna lead from the rear of the radio, and remove radio.
- 8. Re-assemble dash in reverse order.

2011-2014 SCION TC

DASH DISASSEMBLY

- 1. Carefully pull forward and remove the trim panel surrounding the radio, disconnect the attached wire harness and remove trim panel.
- 2. Remove the (4) 10mm bolts securing the factory radio to the sub-dash, carefully and pull the radio forward.
- 3. Disconnect all attached wire harnesses and the antenna lead and remove radio.

2007-11 TOYOTA YARIS - 3 DOOR LIFTBACK ONLY

DASH DISASSEMBLY

- 1. Starting from lower edges, unclip the left and right side trims from around the radio and climate controls, disconnect the attached harnesses and remove trims.
- 2. Carefully unclip and pry forward the lower edge of the instrument gauge trim bezel.
- 3. Carefully unclip and pull forward the Radio/Vent trim bezel and remove.
- 4. Remove the (4) Phillips screws securing the radio to the sub-dash.
- 5. Pull radio forward, disconnect the attached wire harness and antenna lead and remove radio.

2007-11 TOYOTA YARIS - 4 DOOR SEDAN ONLY

DASH DISASSEMBLY

- 1. Carefully unclip and remove the bottom edge trim piece from below the climate control module.
- 2. Starting from lower edges, unclip the left and right side trims from around the radio and climate controls and remove.
- 3. Carefully unclip and pry forward the lower edge of the instrument gauge trim bezel.
- 4. Carefully unclip and pull forward the Radio/Vent trim bezel, disconnect the attached harness and remove bezel.
- 5. Remove the (4) Phillips screws securing the radio to the sub-dash.
- 6. Pull radio forward, disconnect the attached wire harness and antenna lead and remove radio.

2012-14 TOYOTA YARIS

DASH DISASSEMBLY

- 1. Carefully unclip and remove the soft trim piece from around the radio, airbag light/hazard button and passenger side air vent.
- 2. Carefully unclip and pry forward the radio trim bezel.
- 3. Remove the (4) Phillips screws securing the radio to the sub-dash.
- 4. Pull radio forward, disconnect the attached wire harness and antenna lead and remove radio.

2012 SCION IQ

DASH DISASSEMBLY

- 1. Carefully unclip and remove the panel with ac vents from around the hazard button. Unplug hazard button.
- 2. Carefully unclip and pry forward the radio trim housing. Do not unplug Airbag light.
- 3. Place the housing on the dash(you can use something to protect the dash) while installing new radio.
- 5. Remove the (4) 10mm bolts securing the radio to the sub-dash.
- 6. Pull radio forward, disconnect the attached wire harness and antenna lead and remove radio.

2013-14 SCION FR-S

DASH DISASSEMBLY

- 1. Carefully unclip and remove the panel surrounding the radio.
- 2. Remove the (4) 10mm bolts securing the radio to the sub-dash.
- 3. Pull radio forward, disconnect the attached wire harness and antenna lead and remove radio.

- 10. Carefully unclip the entire radio/climate control trim bezel, disconnect all harnesses from bezel and remove.
- 11. Remove the (2) 10mm bolts securing the factory radio to the sub-dash.
- 12. Carefully pull radio forward, disconnect all harnesses and antenna leads and remove radio.

2001-05 TOYOTA RAV4

- 1. Remove the (4) chrome allen bolts securing the radio trim bezel.
- 2. Gently unsnap the radio trim bezel and remove.
- 3. Remove the (4) 10mm bolts securing the radio to the sub-dash.
- 4. Gently pull the radio forward.
- 5. Disconnect the harness and antenna lead from the radio and remove the radio

2001-07 TOYOTA HIGHLANDER

- 1. Starting from the bottom carefully unsnap and remove trim bezel from around climate controls and radio.
- 2. Remove (6) 10mm bolts securing entire climate controls / radio to sub-dash.
- 3. Pull the entire assembly forward, disconnect all harnesses and antenna lead, and remove assembly.
- 4. Remove the (8) phillips screws securing factory radio to assembly brackets and remove factory radio.

2004-06 SCION xA

- 1. Carefully pull outward on the left and right (rotary) climate control knobs and remove the phillips screw from behind each knob.
- 2. Carefully unclip and remove the side trims from beside the climate controls, ashtray, and pocket.
- 3. Remove the (2) phillips screws securing the lower edges of the climate control/radio trim bezel to the sub-dash.
- 4. Carefully pry outward on the Climate control/radio trim bezel, disconnect all harnesses and remove trim bezel.
- 5. Remove the (4) Phillips screws securing the factory radio to the sub-dash. Carefully pull radio forward, disconnect the wire harness and antenna lead from the radio and remove radio.

2004-07 SCION xB

- 1. Carefully pull outward on the left and right (rotary) climate control knobs and remove the Phillips screw from behind each knob.
- 2. Starting from the bottom of the Radio/Climate control trim bezel, pull the left and right side lower edges outward to release the lower clips.
- 3. Continue to pull the Radio/Climate control trim bezel outward and downward to release the upper top clips.
- 4. Pull the Radio/Climate control trim bezel outward and disconnect all harnesses from the rear of the bezel and remove bezel.
- 5. Remove the (4) Phillips screws securing the radio to the sub-dash.
- 6. Carefully pull the radio forward, disconnect the wire harness and antenna lead and remove radio.

2008-12 SCION xB

- 1. Carefully unsnap the rectangle bezel surrounding the factory radio
- 2. Remove (4) 10mm bolts securing the factory radio in
- 3. Disconnect all harnesses and remove radio from dash